

Memorandum

U.S. Department of Transportation

Federal Railroad Administration

Date: June 15, 1998 Reply to Att. of: MP&E 98-64

Subject: Auxiliary Lights Interfering With Safety Appliances

From: Edward R. English
Director, Office of Safety Assurance and Compliance

To: Regional Administrators, Deputy Regional Administrators, Motive Power & Equipment Specialists and Inspectors

It has recently been brought to our attention that some railroads have had the auxiliary lights (ditch lights) installed in a manner which covers a portion of the uncoupling levers, which serve as the end handhold on a locomotive.

Locomotives found in non-compliance should be handled for correction.